

The stepper motor may require a different operational voltage and current provided by the digital controlling system. In this case, an external power supply should provide the proper voltage and current levels.

As our selected stepper motor works with a 5v voltage level, we should use an external power supply.